

Forest Service Mesa Ranger District


5140 East Ingram Street MesaAZ85205 480-610-3300480-610-3346

File Code:

2210; 2240

Date:

November 5, 2018



This letter is a supplement to your Memorandum of Understanding, Cottonwood East, to clean out and rebuild dam and spillway of the selected stock tank, Cane Spring tank improvement number 2207, on the Sunflower Allotment.


Of the tanks listed above, all have been inspected by the Range Specialist for cultural clearance. You are authorized to begin work immediately while still operating within the guidelines of Memorandum of Understanding.

Scope of work:

All leftover materials from maintenance must be removed from the work site. Work will not proceed if soils are saturated. Remove all silt from the stock tank but do not take extra measures to make the tank larger or expand the footprint of the disturbance. Keep all disturbance within the existing footprint of the stock tank and only access the stock tank with equipment using existing Forest Service roads or access routes. Where necessary, remove vegetation from the constructed dam and from within the basin. Scatter any removed material on the downhill side of the dam.



Location of Work:



Sincerely,

GARY HANNA

District Ranger